

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information

Subwatershed:	Unnamed Tributa	iry					
Location of Catch	ment Centroid on A	ADC Map:	Year:	2000	Page: <u>17</u>	Grid:	J8
State Plane Coord	dinates of Outfall L	ocation:	X:	1398057		Y: <u>481465</u>	
Closest Road Inte	ersection to Outfall:	Priest Bridge	Road and I	Espey Cou	ırt		
Outfall SDI ID or (Outfall Description:	unknown					
Objective: Demo	nstration / Impairm	ent(s) (Sheet ²	1) _				
Drainage Area (ad	c): <u>2.0</u>		Imperv	vious Area	a (ac): <u>1.2</u>	5	
Percent Imperviou	us: <u>63%</u>		Soil Re	echarge F	actor (S): 0.3	8	
WQ_v (required):	0.10		Re _v (re	equired):	0.04		
Predominant Land	d Use: <u>commercial</u>		Mean I	Depth to (Ground Water:	unknown	
Sanitary System:	Septic 🗸 Mun	icipal Sewer	Water	Supply:	On Site Well	✓ Public Water	
Storm Drainage	e System Within	Catchment					
Piped: 100%	6 Open	Channels:	0%				
Area Drained by S	System:	100%					
Location in Catch	ment: Headwater	s Middle	Lower	✓ All			
Open Channel Lir	ning- Vegetation:	0%	Riprap:	0%	Concrete:	0% Other:	0%
Existing IMP(s)	/ BMP(s)						
	Type (numb	er from Shee	ts 4 & 5):_		Age:		
	ersection to IMP / B						
Catchment Area	Treated (ac) :		Per	centage (Catchment Trea	ited:	
WQ _v Provided:	YES NO	Re _v Provide	d: 🗌 YES	NO	C _p Provide	d: YES	NO
SDI ID:	Type (numb	er from Shee	ts 4 & 5):_		Age:		
Closest Road Inte	ersection to IMP / B	MP:					
Catchment Area	Treated (ac) :		Per	centage (Catchment Trea	ited:	
WQ _v Provided:	YES NO	Re _v Provide	d: 🗌 YES	NO	C _p Provide	d: Yes	NO
SDI ID:	Type (numb	er from Shee	ts 4 & 5):_		Age:		
Closest Road Inte	ersection to IMP / B	MP:					
Catchment Area	Treated (ac) :		Per	centage (Catchment Trea	ited:	
WQ _v Provided:	YES NO	Re _v Provide	d: 🗌 YES	NO	C _p Provide	d: YES	NO

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information (concluded)

CATCHMENT SUMMARY					
WQ _v (provided):	0.079	Re _v (provided) :	0.079		
Area Treated (ac):	1.49	Impervious Area Treated (ac):	1.24		
Area Treated (%):	75%	Impervious Area Treated (%):	99%		

Comments

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information

Site Name: Richardson Building	Address: 2127 Espey Court
Site Owner: King Commercial Properties 301-345-630	0
State Plane Coordinates of Site Centroid: X	: <u>1398104</u> Y: <u>481686</u> Date: <u>5/27/03</u>
Personnel: PM	Weather: <u>cloudy, rain 65F deg</u>
Area (ac): 2	Impervious Area (ac): <u>1.2</u>
Percent Impervious: <u>62%</u>	Soil Recharge Factor (S): 0.38
WQ _v (required): 0.1	Re _v (required): 0.04
Property Area (ac): 2	Property Area Included in Site: 100%
Amount of Catchment Occupied by Site: 100%	_
Storm Drainage System Within Site Piped: <u>100%</u> Open Channels: <u>09</u>	Area Drained by System: <u>100%</u>
Open Channel Lining - Vegetation:0% Riprap	.: <u>0%</u> Concrete: <u>0%</u> Other: <u>0%</u>
	on: Excellent Good Average Fair Poor on: Excellent Good Average Fair Poor
Site Information	
Type of Pavement: Image: Bituminous Concrete Image: Concret Image: Concrete Image: Concret	Gravel Grid Pavers Other
Pavement Condition: <pre> Excellent</pre>	Average Fair Poor
Underdrains can be easily directed to existing storr	m drains or daylighted: yes NO
Gutter/Exterior Downspouts Present:	✓ NO
Roof Connected Directly to Storm Drain:	NO
Roof Drains onto Impervious Surface:	
Obvious Existing Drainage Problems:	ensive 🗌 Moderate 🗌 Average 🗹 Limited 🗌 None
Steep Slopes Present:	ate 🗌 Average 🗌 Limited 🗹 None
Existing Landscaping:	ate 🗹 Average 🗌 Limited 🗌 None
Mature / Specimen Trees:	ate 🗹 Average 🗌 Limited 🗌 None
Area Available for Aboveground BMPs:	ensive 🗹 Moderate 🗌 Average 🗌 Limited 🗌 None
Existing Cover of Potential Aboveground BMP Loca	ations: Image: Grass in the constraint of the constraint

Impervious Area Treated (%):

100%

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)

Commercial / Institutional						
Islands Present: 🖂 🛛	ES 🗌 NO	Curb Present Around Island:	YES NO			
Ground Level of Islan	d Relative to Pavement:	Above Equal Below				
Island Landscaping:	sland Landscaping: Impervious Bare Earth Gravel Grass Mulch Herbaceous Plants Shrubs Trees (<2 in. DBH) Trees (2 - 6 in. DBH) Trees (>6 in. DBH)					
Trees have sufficient	spacing to allow IMPs	YES VNO				
Parking area that can	Parking area that can be directed to potential treatment area with little grading: <u>95%</u>					
SITE SUMMARY						
WQ_v (provided) :	0.079	Re _v (provided):	0.079			
Area Treated (ac) :	1.49	Impervious Area Treated (ac):	1.24			

Photographs

Area Treated (%) :

75%

No.	3	Description: looking north along west side of property
No.	4	Description: looking east along south side of property
No.	5	Description: looking north along east side of property
No.	6	Description: looking west along south side of property
No.	7	Description: looking west along north side of property
No.	8	Description: looking south along east side of property
No.	9	Description: looking east along north side of property
No.	10	Description: looking south along west side of property
No.	11	Description: north side of building
No.		Description:

Comments Parking is needed along the east side of 2131. West side is more commercial and does

not appear that customer parking is needed. Most of the parking is for fleet vehicles and employees. However, there does not appear to be surplus parking.

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information











UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)





9





New LID IMP SWM BMP Retrofit	SWM BMP 🗆	Type (Sheets 4 & 5):	7
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398142</u>	Y:	481668
Sketch Location of Footprint (with Approximate Dimen	sions) and Drainage	Boundary on Site Ma	p
Identify all Impairments Addressed by Recommendation	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW County	Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🔽 NO		
Limited Impact to Adjacent Properties:)		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: YES NO			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:YESNO			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tele	phone 🗌 Cable 🗌 Wat	er 🗌 Sewer 🗌 Other	
Utilities Impacted: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tele	phone 🗌 Cable 🗌 Wat	er Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: 🗌 YES 🔽 NO			
Mature / Specimen Trees Impacted:YESNO			
Existing Landscaping Impacted:			
Underdrain Needed: VES VO Under	rdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable: YES NO Groun	nd Water Table Leve	I Suitable: 🗌 YES	NO
Estimate IMP / BMP drainage area included on site:	<u>0.25</u> ad	>	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture:	Add Aquatic Bench	YES NO	
Grade Bottom of Facility:	Plant Native Vegeta	ation: YES NO	
Provide Additional Storage Volume: yes No			
Excavation / Raise the Embankment:	0		

	IMP / BMP SUMMA			
Photographs No. 11 Description: north side of building No. Description: north side of building north side of building Comments	WQ _v (provided): ur	nknown	Re _v (provided):	0.000
No. 11 Description: north side of building No.	Area Treated (ac):	0.25	Impervious Area Treated (ac):	0.25
No. Description:	Photographs			
No. Description:	No. <u>11</u>	Description:	north side of building	
No. Description:	No.	Description:		
No. Description: No. Description: No. Description: No. Description: No. Description: No. Description:	No.	Description:		
No. Description: No. Description: No. Description: No. Description:	No.	Description:		
No Description: No Description: Comments	No.	Description:		
No. Description: No. Description: Comments	No.	Description:		
Comments				
	No.	Description:		
	Comments			
	IMP size = 10,714 sq			



New LID IMP ☑ SWM BMP Retrofit □ New	SWM BMP \Box	Type (Sheets 4 & 5):	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1397985</u>	Y:	481691
Sketch Location of Footprint (with Approximate Dime	nsions) and Drainage	Boundary on Site Ma	ар
Identify all Impairments Addressed by Recommendat	ion (Sheet 1):		
Treatment Area Ownership:	Utility ROW Count	y Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗸 NO		
Limited Impact to Adjacent Properties:	0		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: I YES NO			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:YESNO			
Forest Retention Area Impacted:			
Conservation Easement Impacted:YESNO			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🗌 Te	ephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Utilities Impacted: 🗌 None 🗌 Natural Gas 🗹 Electric 🗌 Te	ephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Impacted Utilities: Above Gound Inderground			
Critical Area Impacted: VES VNO			
Mature / Specimen Trees Impacted: VES NO			
Existing Landscaping Impacted:			
Underdrain Needed: YES VO Under	erdrains Can Dischar	ge: Yes No	
Soils are Suitable: VES NO Grou	nd Water Table Leve	el Suitable: 🖂 YES	NO
Estimate IMP / BMP drainage area included on site:	<u>0.16</u> a	C	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: VES NO	Add Aquatic Bench	n: 🗌 yes 🗌 no	
Grade Bottom of Facility: YESNO	Plant Native Veget	ation: YES NO	
Provide Additional Storage Volume:YESNO			
Excavation / Raise the Embankment:	NO		

IMP / BMP SUMMARY			
WQ _v (provided):	0.010	Re _v (provided):	0.010
Area Treated (ac):	0.16	Impervious Area Treated (ac):	0.13
Photographs			
No. <u>12</u>	Description:	looking west	
No. <u>13</u>	Description:	looking south	
No.	Description:		
No	Description:		
Comments			
IMP size = 909 sq ft			







New LID IMP SWM BMP Retrofit New		Type (Sheets 4 & 5):	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398023</u>	Y:	481575
Sketch Location of Footprint (with Approximate Dimer	sions) and Drainage	Boundary on Site Ma	p
Identify all Impairments Addressed by Recommendati	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW Count	y Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties: VES N	C		
Area Accessible for Construction:			
Area Accessible for Maintenance:			
Limited Permitting Issues: yes NO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🗌 Tele	ephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Utilities Impacted: None Natural Gas Selectric Tele	ephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Impacted Utilities: Above Gound			
Critical Area Impacted: VES VNO			
Mature / Specimen Trees Impacted: YES NO			
Existing Landscaping Impacted: yes INO			
Underdrain Needed: YES VO Under	rdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable: 🖓 YES 🗌 NO Grou	nd Water Table Leve	el Suitable: 🖂 YES	NO
Estimate IMP / BMP drainage area included on site:	<u>0.31</u> a	с	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: VES NO	Add Aquatic Bench	I: YES NO	
Grade Bottom of Facility: YESNO	Plant Native Veget	ation: YES NO	
Provide Additional Storage Volume: YES NO			
Excavation / Raise the Embankment:	10		

018).31	Re _v (provided):	0.018
).31	Impervious Area Treated (ac):	
		0.21
Description:	looking south	
Description:	looking west	
Description:	looking north	
Description:		
	Description: Description: Description: Description: Description: Description:	Description:looking westDescription:looking northDescription:





14

15



New LID IMP ☑ SWM BMP Retrofit □ New	SWM BMP	Type (Sheets 4 & 5):	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398246</u>	Y:	481656
Sketch Location of Footprint (with Approximate Dime	nsions) and Drainage	Boundary on Site Ma	р
Identify all Impairments Addressed by Recommendat	ion (Sheet 1):		
Treatment Area Ownership: Transportation ROW	Utility ROW County	Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties:	10		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance:			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted: YES NO			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: None Natural Gas Electric Te	lephone 🗌 Cable 🗹 Wat	er Sewer Other	
Utilities Impacted: None Natural Gas Electric Te	lephone 🗌 Cable 🗹 Wat	er Sewer Other	
Impacted Utilities: Above Gound			
Critical Area Impacted: YES NO			
Mature / Specimen Trees Impacted:			
Existing Landscaping Impacted:			
Underdrain Needed: VES VO Underdrain	erdrains Can Discharg	Je: Yes NO	
Soils are Suitable: VES NO Grou	ind Water Table Leve	I Suitable: ☑ _{YES} [NO
Estimate IMP / BMP drainage area included on site:	<u>0.27</u> a0	;	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: Set No	Add Aquatic Bench	YES NO	
Grade Bottom of Facility: YESNO	Plant Native Vegeta	ation: YES NO	
Provide Additional Storage Volume:YESNO			
Excavation / Raise the Embankment:	NO		





18

New LID IMP SWM BMP Retrofit	SWM BMP 🗌	Type (Sheets 4 & 5):	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398034</u>	Y:	481842
Sketch Location of Footprint (with Approximate Dimen	sions) and Drainage	Boundary on Site Ma	p
Identify all Impairments Addressed by Recommendation	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW County	Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗸 NO		
Limited Impact to Adjacent Properties:	D		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: YES NO			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🗹 Tele	ephone 🗌 Cable 🗹 Wat	er 🗌 Sewer 🗌 Other	
Utilities Impacted: None Natural Gas Selectric Stee	ephone 🗌 Cable 🗌 Wat	er 🗌 Sewer 🗌 Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: 🗌 YES 🔽 NO			
Mature / Specimen Trees Impacted:YESNO			
Existing Landscaping Impacted:			
Underdrain Needed: YES VO Unde	rdrains Can Discharg	je: YES NO	
Soils are Suitable: 🖓 YES 🗌 NO Ground	nd Water Table Leve	I Suitable: VES	NO
Estimate IMP / BMP drainage area included on site:	<u>0.46</u> ac	2	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture:	Add Aquatic Bench	YES NO	
Grade Bottom of Facility:	Plant Native Vegeta	ation: YES NO	
Provide Additional Storage Volume: yes No			
Excavation / Raise the Embankment:	0		

IMP / E		(
WQ _v (provided): Area Treated (ac):		0.033	Re _v (provided):	0.033 0.42
		0.46	Impervious Area Treated (ac):	
Photo	graphs			
No.	19	Description:	looking west	
No.	20	Description:	looking north	
No.	21	Description:	looking east	
No.	22	Description:	looking east along Espey Court	
No.		Description:		
Comm IMP siz	ents <u>"Spe</u> e = 2,910 sq ft	ed bumps" must be used to	direct flow.	





19

20





21

New LID IMP ☑ SWM BMP Retrofit □ New S		Type (Sheets 4 & 5):	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1397948</u>	Y:	481828
Sketch Location of Footprint (with Approximate Dimen	sions) and Drainage	Boundary on Site Ma	р
Identify all Impairments Addressed by Recommendation	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW County	Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties:)		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: YES NO			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:YESNO			
Forest Retention Area Impacted:			
Conservation Easement Impacted:YESNO			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🗹 Tele	phone 🗌 Cable 🗹 Wate	er Sewer Other	
Utilities Impacted: None Natural Gas Selectric Selectric	phone 🗌 Cable 🗌 Wate	er Sewer Other	
Impacted Utilities: Above Gound Inderground			
Critical Area Impacted: YES VINO			
Mature / Specimen Trees Impacted:YES NO			
Existing Landscaping Impacted:			
Underdrain Needed: VES VNO Under	rdrains Can Discharg	e: Yes No	
Soils are Suitable: 🖸 YES 🗌 NO Groun	nd Water Table Level	Suitable: 🗸 YES [NO
Estimate IMP / BMP drainage area included on site:	<u>0.04</u> ac		100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: VES NO	Add Aquatic Bench:	YES NO	
Grade Bottom of Facility: YESNO	Plant Native Vegeta	tion: 🗌 yes 🗌 no	
Provide Additional Storage Volume: YES NO			
Excavation / Raise the Embankment: \Box_{YES}	0		

ovided):	0.003	Re _v (provided):		
ated (ac):	0.04	Impervious Area Treated (ac):	0.04	
raphs				
23	Description:	looking south		
24	Description:	looking east		
25	Description:	looking south		
	Description:			
-	"Speed bumps" must be used to a	direct flow.		
	eated (ac):	eated (ac): 0.04 raphs 23 Description: 24 Description: Description: 25 Description: Description: 26 Description: Description: 25 Description: Description:	nated (ac): 0.04 Impervious Area Treated (ac): raphs 23 Description: looking south 24 Description: looking east 25 Description: looking south 25 Description: looking south 26 Description: looking south 25 Description: looking south 26 Description: looking south 27 Description: looking south 28 Description: looking south 29 Description: looking south 20 Description: looking south 20 Description: looking south 20 Description: looking south 21 Description: looking south 22 Description: looking south 23 Description: looking south 24 </td	





23

24

