

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information

Subwatershed: Unnamed Tributary	_				
Location of Catchment Centroid on ADC Map	p: Year:	2000	Page: <u>17</u>	Grid:	J8
State Plane Coordinates of Outfall Location:	X: <u> </u>	1398264		Y: <u>482053</u>	
Closest Road Intersection to Outfall: Priest E	Bridge Drive and E	Espey Court			
Outfall SDI ID or Outfall Description: unknow	'n				
Objective: Demonstration / Impairment(s) (S	heet 1)				
Drainage Area (ac): <u>6.0</u>	Imperv	ious Area (a	c): <u>0.8</u>		
Percent Impervious: <u>13%</u>	Soil Re	charge Fact	or (S): <u>0.38</u>		
WQ _v (required): 0.09	Re _v (re	quired): 0.03	3		
Predominant Land Use: <u>commercial</u>	Mean [Depth to Gro	und Water:	unknown	
Sanitary System: Septic Municipal Sewer	r Water	Supply:	On Site Well	Public Water	
Storm Drainage System Within Catchn	nent				
Piped: <u>100%</u> Open Channe	els: <u>0%</u>				
Area Drained by System: 100%	<u>)</u>				
Location in Catchment: Headwaters	/liddle Lower				
Open Channel Lining- Vegetation:	0% Riprap:	<u>0%</u> C	Concrete:	0% Other:	0%
Existing IMP(s) / BMP(s)					
SDI ID: Unknown Type (number from S	Sheets 4 & 5): _	13	Age:		
Closest Road Intersection to IMP / BMP:	Priest Bridge F	Road and Es	pey Court		
Catchment Area Treated (ac) :	Per	centage Cate	chment Treat	ed:	
WQ _v Provided: YES V NO Re _v Provided:	ovided: YES	✓ NO	C _p Provided	: YES	✓ NO
SDI ID: Type (number from S	Sheets 4 & 5):		Age:		
Closest Road Intersection to IMP / BMP:					
Catchment Area Treated (ac) :	Per	centage Cate	chment Treat	ed:	
WQ _v Provided: YES NO Re _v Provided:	ovided: YES	NO	C _p Provided	: YES	NO
SDI ID: Type (number from S	Sheets 4 & 5): _		Age:		
Closest Road Intersection to IMP / BMP:					
Catchment Area Treated (ac) :	_ Per	centage Cate	chment Treat	ed:	
WQ _v Provided: \Box YES \Box NO Re _v Provided:	ovided: YES	NO	C _p Provided	I: YES	NO

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information (concluded)

CATCHMENT SUMMARY				
WQ_v (provided):	0.024	Re _v (provided) :	0.024	
Area Treated (ac):	0.81	Impervious Area Treated (ac):	0.65	
Area Treated (%):	14%	Impervious Area Treated (%):	81%	

CommentsThe storm water management treats about three quarters of the property, which includesthe roof. The drainage area of the facility cannot be determined because the storm drainage systemis not known.

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information

Site Name:	Address: 2130 Priest Bridge Drive
Site Owner:	
State Plane Coordinates of Site Centroid:	X: <u>1398409</u> Y: <u>481682</u> Date: <u>5/28/03</u>
Personnel: PM	Weather: <u>cloudy</u> , 70F deg
Area (ac): <u>6</u>	Impervious Area (ac): <u>0.8</u>
Percent Impervious: 14%	Soil Recharge Factor (S): 0.38
WQ _v (required): 0.09	Re_v (required): 0.03
Property Area (ac): 6.4	Property Area Included in Site: 93%
Amount of Catchment Occupied by Site:	100%
Storm Drainage System Within Site	
Piped: <u>100%</u> Open Channels:	0% Area Drained by System: 75%
Open Channel Lining - Vegetation: 0%	Riprap: 0% Concrete: 0% Other: 0%
Existing IMP(s) / RMP(s) (Indentified (on Page 1, FORM 1, Catchment Information)
	Condition: Excellent Good Average Fair Poor
	Condition: Excellent Good Average Fair Poor
SDI ID:	Condition: Excellent Good Average Fair Poor
Site Information	
Type of Pavement: Bituminous Conc	rete Gravel Grid Pavers Other
Pavement Condition:	Good Average Fair Poor
Underdrains can be easily directed to exist	ing storm drains or daylighted:
Gutter/Exterior Downspouts Present:	YES VO
Roof Connected Directly to Storm Drain: [YES NO
Roof Drains onto Impervious Surface:	YES NO
Obvious Existing Drainage Problems:	Extensive Moderate Average Limited Vone
Steep Slopes Present:	Moderate Average Limited Vone
Existing Landscaping:	Moderate Average Limited None
Mature / Specimen Trees:	Moderate Average Limited None
Area Available for Aboveground BMPs:	Extensive Moderate Average Limited None
Existing Cover of Potential Aboveground B	

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)

Commercial / Institutional				
Islands Present: VES NO	Curb Present Around Island: VES NO			
Ground Level of Island Relative to Paveme	ent: Above Equal Below			
Island Landscaping: Impervious Bare	e Earth Gravel Grass Image: Mulch Herbaceous Plants Image: Shrubs Trees (2 - 6 in. DBH) Trees (>6 in. DBH)			
Trees have sufficient spacing to allow IMPs	S YES NO			
Parking area that can be directed to potential treatment area with little grading: 40%				
SITE SUMMARY				

WQ_v (provided) :	0.024	Re _v (provided):	0.024
Area Treated (ac) :	0.81	Impervious Area Treated (ac):	0.65
Area Treated (%) :	14%	Impervious Area Treated (%):	81%

Photographs

No.	205	Description: looking north to SWM riser
No.	206	Description: looking east across SWM pond
No.	207	Description: looking south along west side of property
No.	208	Description: looking east along north side of property
No.	209	Description: looking east along south side of property
No.	210	Description: looking north along west side of property
No.	211	Description: looking north along east side of property
No.	212	Description: looking south along east side of property
No.	213	Description: looking west along north side of property
No.	214	Description: looking west along south side of property

Comments Inlet along east side of building cannot be retrofitted because they are not adjacent to curb. Pavement is too new to be replaced with grid pavers. There appears significant room to expand the existing SWM pond to the north and east.

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information





205





207



208



209

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)





211









New LID IMP SWM BMP Retrofit		Type (Sheets 4 & 5):	7
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398366</u>	Y:	481835
Sketch Location of Footprint (with Approximate Dimen	sions) and Drainage	Boundary on Site Ma	р
Identify all Impairments Addressed by Recommendation	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW County	/ Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗸 NO		
Limited Impact to Adjacent Properties:)		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: YES NO			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:YESNO			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tele	phone 🗌 Cable 🗌 Wat	er Sewer Other	
Utilities Impacted: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tele	phone 🗌 Cable 🗌 Wat	er Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: 🗌 YES 🔽 NO			
Mature / Specimen Trees Impacted:YES NO			
Existing Landscaping Impacted:			
Underdrain Needed: VES VNO Under	rdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable: YES NO Groun	nd Water Table Leve	I Suitable:YES [NO
Estimate IMP / BMP drainage area included on site:	<u>0.35</u> a	с	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture:	Add Aquatic Bench	: YES NO	
Grade Bottom of Facility:	Plant Native Vegeta	ation: YES NO	
Provide Additional Storage Volume: YES NO			
Excavation / Raise the Embankment:	0		

IMP /	BMP SUM	MARY		
WQ _v (provided): unknown Area Treated (ac):		unknown		Re _v (provided): 0.00
		0.35		Impervious Area Treated (ac): 0.3
Photo	ographs			
No.	216	[Description:	front of building
No.	215	[Description:	rear of building showing scuppers
No.		[Description:	
No.		[Description:	
No.		[Description:	
No.		[Description:	
No.		[Description:	
No.		[Description:	
Comn	nents	Building is less than	2 years old a	and a green roof may not be appropriate at this time.
	ze = 15,438			





215

New LID IMP SWM BMP Retrofit		Type (Sheets 4 & 5):	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398244</u>	Y:	481904
Sketch Location of Footprint (with Approximate Dimen	sions) and Drainage	Boundary on Site Ma	p
Identify all Impairments Addressed by Recommendati	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW Count	y Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🔽 NO		
Limited Impact to Adjacent Properties: VES No)		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: YES NO			
Limited Permitting Issues: yes NO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🗹 Tele	ephone 🗌 Cable 🗹 Wa	ter Sewer Other	
Utilities Impacted: None Natural Gas I Electric Tele	ephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: VES VO			
Mature / Specimen Trees Impacted:YESNO			
Existing Landscaping Impacted:			
Underdrain Needed: YES VO Under	rdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable: I YES NO Group	nd Water Table Leve	el Suitable: 🖂 YES	NO
Estimate IMP / BMP drainage area included on site:	<u>0.11</u> a	С	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture:	Add Aquatic Bench	E YES NO	
Grade Bottom of Facility:YESNO	Plant Native Veget	ation: YES NO	
Provide Additional Storage Volume: yes No			
Excavation / Raise the Embankment:	0		

IMP /	BMP SUM	MARY	
WQ _v (provided): 0.008		0.008	Re _v (provided): 0.008
Area T	reated (ac)	0.11	Impervious Area Treated (ac): 0.10
Photo	ographs		
No.	217	Description:	looking south
No.	218	Description:	looking east
No.	219	Description:	looking north
No.		Description:	
Comn	nents	A speed bump will be needed to	direct flow. A water meter box precluded use of the
area to	o the east. /	Additional IMP exists to the south b	out must cross under a concrete sidewalk with a
pipe or	r a trench dr	rain.	
IMP siz	ze = 695 sq	ft	





217





New LID IMP ☑ SWM BMP Retrofit □ New	SWM BMP 🗌	Type (Sheets 4 & 5):	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398304</u>	Y:	481745
Sketch Location of Footprint (with Approximate Dimer	nsions) and Drainage	Boundary on Site Ma	р
Identify all Impairments Addressed by Recommendat	ion (Sheet 1):		
Treatment Area Ownership:	Utility ROW County	Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties:	0		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: YES NO			
Limited Permitting Issues: yes NO			
Jurisdictional Wetlands Impacted:YESNO			
Forest Retention Area Impacted:			
Conservation Easement Impacted:YESNO			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🗹 Tel	ephone 🗌 Cable 🗹 Wat	er Sewer Other	
Utilities Impacted: None Natural Gas I Electric Tel	ephone 🗌 Cable 🗌 Wat	er Sewer Other	
Impacted Utilities: Above Gound Inderground			
Critical Area Impacted: 🗌 YES 🗹 NO			
Mature / Specimen Trees Impacted: YES NO			
Existing Landscaping Impacted:			
Underdrain Needed: VES VO Under	erdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable: VES NO Grou	nd Water Table Leve	I Suitable: VES [NO
Estimate IMP / BMP drainage area included on site:	<u>0.35</u> a		100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: YES NO	Add Aquatic Bench	YES NO	
Grade Bottom of Facility: YESNO	Plant Native Vegeta	ation: YES NO	
Provide Additional Storage Volume: yes No			
Excavation / Raise the Embankment:	NO		

IMP / B	MP SUMMARY		
WQ _v (pr	ovided):	0.016	Re _v (provided): 0.016
Area Tre	Treated (ac): 0.35 Impervious Area		Impervious Area Treated (ac): 0.20
Photog	graphs		
No.	222	Descript	ion: looking east
No.	223	Descript	ion: <u>looking north</u>
No.	224	Descript	ion: <u>looking south</u>
No.		Descript	ion:
Comm	ents The co	ncrete sidewalk will r	need to be spanned with a pipe or concrete trench drain.
A speed	l bump will be nee	ded to direct flow. A	water meter box precluded use of the area to the east.
Addition	al IMP exists to the	e south but must cros	ss under a concrete sidewalk with a pipe or a trench

drain.

IMP size = 1,404 sq ft





222

223



New LID IMP ☑ SWM BMP Retrofit □ New	SWM BMP \Box	Type (Sheets 4 & 5):	59
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398301</u>	Y:	481815
Sketch Location of Footprint (with Approximate Dime	nsions) and Drainage	Boundary on Site Ma	ıp
Identify all Impairments Addressed by Recommendat	ion (Sheet 1):		
Treatment Area Ownership:	Utility ROW Count	y Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties:	10		
Area Accessible for Construction:			
Area Accessible for Maintenance:			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🖓 Te	lephone 🗌 Cable 🗹 Wa	ter Sewer Other	
Utilities Impacted: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Te	lephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: VES VO			
Mature / Specimen Trees Impacted:			
Existing Landscaping Impacted:			
Underdrain Needed: VES VO Underdrain	erdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable:YESNO Grou	ind Water Table Leve	el Suitable: 🗌 YES	NO
Estimate IMP / BMP drainage area included on site:	a	С	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:] YES 🗌 NO	
Modify Outlet Stucture: Stucture: NO	Add Aquatic Bench	: YES NO	
Grade Bottom of Facility:YESNO	Plant Native Veget	ation: YES NO	
Provide Additional Storage Volume: YES NO			
Excavation / Raise the Embankment:	NO		

IMP / BMP SUMMARY	
WQ _v (provided):	Re _v (provided):
Area Treated (ac):	Impervious Area Treated (ac):

Photographs

No.	220	Description:	looking south
No.	221	Description:	looking north
No.		Description:	

Comments

IMP size = 8,814 sq ft





220

New LID IMP ☑ SWM BMP Retrofit □ New	SWM BMP	Type (Sheets 4 & 5):	52
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398301</u>	Y:	481815
Sketch Location of Footprint (with Approximate Dime	nsions) and Drainage	Boundary on Site Ma	р
Identify all Impairments Addressed by Recommendat	ion (Sheet 1):		
Treatment Area Ownership: Transportation ROW	Utility ROW Count	y Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗸 NO		
Limited Impact to Adjacent Properties:	10		
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance:			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🖓 Te	lephone 🗌 Cable 🗹 Wa	ter Sewer Other	
Utilities Impacted: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Te	lephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: VES VO			
Mature / Specimen Trees Impacted:			
Existing Landscaping Impacted:			
Underdrain Needed: YES VO Under	erdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable:YESNO Grou	and Water Table Leve	el Suitable: 🗌 YES [NO
Estimate IMP / BMP drainage area included on site:	a	с _.	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: VES NO	Add Aquatic Bench	: YES NO	
Grade Bottom of Facility: YESNO	Plant Native Veget	ation: YES NO	
Provide Additional Storage Volume:YESNO			
Excavation / Raise the Embankment:	NO		

IMP / BMP SUMMARY	
WQ _v (provided):	Re _v (provided):
Area Treated (ac):	Impervious Area Treated (ac):

Photographs

No.	220	Description:	looking south
No.	221	Description:	looking north
No.		Description:	

Comments

IMP size = 8,814 sq ft





220

New LID IMP SWM BMP Retrofit SWM S		Type (Sheets 4 & 5):	21
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398261</u>	Y:	482051
Sketch Location of Footprint (with Approximate Dimens	ions) and Drainage	Boundary on Site Ma	р
Identify all Impairments Addressed by Recommendatio	n (Sheet 1):		
Treatment Area Ownership:	Utility ROW County	Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	ES 🗌 NO		
Limited Impact to Adjacent Properties:			
Area Accessible for Construction: YES NO			
Area Accessible for Maintenance: VES NO			
Limited Permitting Issues: VES NO			
Jurisdictional Wetlands Impacted:YESNO			
Forest Retention Area Impacted:			
Conservation Easement Impacted:YESNO			
Utilities Present: 🗌 None 🗌 Natural Gas 🗹 Electric 🗸 Telep	hone 🗌 Cable 🗌 Wate	er Sewer Other	
Utilities Impacted: 🗌 None 🗌 Natural Gas 🗹 Electric 🗹 Telep	hone 🗌 Cable 🗌 Wate	er Sewer Other	
Impacted Utilities: Above Gound			
Critical Area Impacted: 🗌 YES 🗹 NO			
Mature / Specimen Trees Impacted:YESNO			
Existing Landscaping Impacted:			
Underdrain Needed: VES VNO Underd	drains Can Discharg	e: Yes NO	
Soils are Suitable: VES NO Ground	d Water Table Level	Suitable: VES [NO
Estimate IMP / BMP drainage area included on site:	a	-	10%
Retrofit of Existing SWM BMP			
SDI ID: unknown	Add Forebay:	YES NO	
Modify Outlet Stucture: VES NO	Add Aquatic Bench:	✓ YES □ NO	
Grade Bottom of Facility: yes NO	Plant Native Vegeta	tion: 🗹 yes 🗌 no	
Provide Additional Storage Volume: VES NO			
Excavation / Raise the Embankment:			

IMP / BMP SUMMARY	
WQ _v (provided):	Re _v (provided):
Area Treated (ac):	Impervious Area Treated (ac):

Photographs

No.	225	Description:	riser and low-flow orifice
No.	226	Description:	looking north across pond
No.	227	Description:	looking east across pond
No.	228	Description:	looking south across pond
No.	229	Description:	looking west at embankment
No.		Description:	
No.		Description:	
No.		Description:	

CommentsAdditional storage capacity can be obtained by grading to the north and to the east.Property and ownership must be confirmed. Pond could be sized to overcontrol because of absenceof SWM throughout the area. Sediment appears to be coming from the Patuxent Materials, Incfacility - possibly from washing vehicles. Riser low-flow inlet is partially blocked. Riser is cracked andconcrete is flaking. Facility will need to be sized to current requirements and to meet dam regulations.



225

226



227



228

