

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information

Subwatershed: Unna	amed Tributary				
Location of Catchment C	Centroid on ADC Map:	Year: 2000	Page: <u>17</u>	Grid: <u>J7</u>	
State Plane Coordinates	of Outfall Location:	X: <u>1398747</u>	7	Y: <u>482359</u>	
Closest Road Intersection	on to Outfall: Defense Highw	ay and Baldwin A	venue		
Outfall SDI ID or Outfall	Description: unknown				
Objective: Demonstration	on / Impairment(s) (Sheet 1)				
Drainage Area (ac):	1.5	Impervious Ar	ea (ac): <u>1.4</u>		
Percent Impervious:	93%	Soil Recharge	e Factor (S): <u>0.38</u>		
WQ _v (required): 0.11		Re_v (required)	: 0.04		
Predominant Land Use:	commercial	Mean Depth to	o Ground Water:	unknown	
Sanitary System: Sep	tic	Water Supply	On Site Well	✓ Public Water	
Storm Drainage Syst	em Within Catchment				
Piped: <u>100%</u>	Open Channels:	0%			
Area Drained by System	n: <u>100%</u>				
Location in Catchment:	Headwaters Middle	Lower 🗸 Al	I		
Open Channel Lining- V	egetation: 0%	Riprap: 0%	Concrete:	0% Other:	0%
Existing IMP(s) / BMF	> (s)				
SDI ID:	Type (number from Sheets	4 & 5):	Age:		
Closest Road Intersectio	on to IMP / BMP:				
Catchment Area Treated	1 (ac) :	Percentage	e Catchment Treat	ed:	
WQ _v Provided: VES	$6 \square NO \qquad \mathbf{Re}_{v} \mathbf{Provided}:$	YES NO	C _p Provided	I: YES I	NO
SDI ID:	Type (number from Sheets	4 & 5):	Age:		
Closest Road Intersection	on to IMP / BMP:				
Catchment Area Treated	d (ac) :	Percentage	e Catchment Treat	.ed:	
WQ _v Provided:	Re_v Provided:	YES NO	C _p Provided	: YES	NO
SDI ID:	Type (number from Sheets	4 & 5):	Age:		
Closest Road Intersection	on to IMP / BMP:				
Catchment Area Treated	1 (ac) :	Percentage	e Catchment Treat	ed:	
WQ _v Provided: YES	Re_v Provided:	YES NO	C _p Provided	E YES	NO

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information (concluded)

CATCHMENT SUI	MMARY		
WQ _v (provided):	0.075	Re _v (provided) :	0.022
Area Treated (ac):	1.47	Impervious Area Treated (ac):	1.33
Area Treated (%):	98%	Impervious Area Treated (%):	95%

Comments

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information

Site Name:		Address: 2101 Defense	Hwy & 211	1 Baldwin Ave
Site Owner:				
State Plane Coordinates of Site Centroid:	X:_	1398822 Y:	482579	Date: <u>5/29/03</u>
Personnel: PM		Weather: <u>cloudy, rain</u> ,	70F deg	
Area (ac): <u>1.4</u>	I	Impervious Area (ac):	1.3	}
Percent Impervious: 96%	;	Soil Recharge Factor (S):		0.38
WQ _v (required): 0.1		Re _v (required):	0.04	
Property Area (ac): 1.4		Property Area Included in	Site:	100%
Amount of Catchment Occupied by Site:	93%			
Storm Drainage System Within Site				
Piped: <u>100%</u> Open Channels:	0%	Area Drained by	System:	100%
Open Channel Lining - Vegetation:	Riprap:	Concrete:		Other:
Existing IMP(s) / BMP(s) (Indentified	-			
SDI ID:			- -	Fair Poor
SDI ID:			- -	Fair Poor
SDI ID:	Condition	Excellent Good /	Average	Fair Poor
Site Information				
Type of Pavement:	crete	Gravel Grid Pavers	Other	
Pavement Condition:	Good	✓ Average Fair	Poor	
Underdrains can be easily directed to exis	ting storm	drains or daylighted:	YES	✓ NO
Gutter/Exterior Downspouts Present:	✓ YES	✓ NO (see commer	nts)	
Roof Connected Directly to Storm Drain:	YES [✓ NO		
Roof Drains onto Impervious Surface:	✓ YES	NO		
Obvious Existing Drainage Problems:	Extens	ive 🗌 Moderate 🗌 Average	e 🗸 Limi	ted None
Steep Slopes Present:	Moderate	Average Limited	✓ None	
Existing Landscaping:	Moderate	Average 🗸 Limited	None	
Mature / Specimen Trees:	Moderate	Average 🗸 Limited	None	
Area Available for Aboveground BMPs:	Extens	ive Moderate Average	e 🗹 Limi	ted None
Existing Cover of Potential Aboveground E	3MP Locati	ONS: Grass Landso	caped Gr	

Impervious Area Treated (%): 100%

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)

Commercial / Instit	utional		
Islands Present: 🗹 YE	ES 🗌 NO	Curb Present Around Island:	YES NO
Ground Level of Island	d Relative to Paveme	ent: Above Equal Below	
Island Landscaping:	Impervious Bare Trees (<2 in. DBH)	e Earth Gravel Grass Mulch Herbaced Trees (2 - 6 in. DBH) Trees (>6 in. DBH)	ous Plants 🗹 Shrubs
Trees have sufficient	spacing to allow IMPs	S YES NO	
Parking area that can	be directed to potent	ial treatment area with little grading:	100%
SITE SUMMARY			
WQ_v (provided) :	0.075	Re _v (provided):	0.022
Area Treated (ac) :	1.47	Impervious Area Treated (ac):	1.33

Photographs

Area Treated (%) :

No.	287	Description: looking north along west side of property
No.	288	Description: looking east along south side of property
No.	289	Description: looking north along east side of property
No.	290	Description: looking west along south side of property
No.	291	Description: looking west between buildings
No.	292	Description: looking west along north side of property
No.	293	Description: looking south along east side of property
No.	294	Description: looking east along north side of property
No.	295	Description: looking south along west side of 2101
No.	296	Description: looking south along west side of 2111

Comments 2101 is drained internally but discharges onto impervious surface.

100%

2111 is drained externally and discharges directly onto impervious surface.
Little opportunity for IMPs because of the topography.

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information





287

288



289



290



291

UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)





293

294





295

New LID IMP ☑ SWM BMP Retrofit □ New	SWM BMP	Type (Sheets 4 & 5):	7
State Plane Coordinates of IMP / BMP Centroid:	X: varies	Y:	varies
Sketch Location of Footprint (with Approximate Dime	nsions) and Drainage	Boundary on Site Ma	o
Identify all Impairments Addressed by Recommendat	ion (Sheet 1):		
Treatment Area Ownership:	Utility ROW Count	y Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗸 NO		
Limited Impact to Adjacent Properties:	0		
Area Accessible for Construction:			
Area Accessible for Maintenance:			
Limited Permitting Issues: IV YES INO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tel	lephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Utilities Impacted: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tel	lephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: VES VNO			
Mature / Specimen Trees Impacted:			
Existing Landscaping Impacted:			
Underdrain Needed: VES VO Under	erdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable: YES NO Grou	nd Water Table Leve	el Suitable: 🗌 YES [NO
Estimate IMP / BMP drainage area included on site:	<u>0.39</u> a	с	100%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: YES NO	Add Aquatic Bench	1: YES NO	
Grade Bottom of Facility:YESNO	Plant Native Veget	ation: YES NO	
Provide Additional Storage Volume:YESNO			
Excavation / Raise the Embankment:	NO		

	MARY		
rovided):	unknown	Re _v (provided):	0.000
eated (ac):	0.39	Impervious Area Treated (ac):	0.39
graphs			
304	Description	n: <u>2101 building</u>	
303	Description	n: 2101 drain	
297	Description	n: 2111 downspouts	
	Description	n:	
ns of IMPs: 398837, Y= 398812, Y=	=482691 =482488	mbined results for 1a and 1b.	
	rovided): eated (ac): graphs 304 303 297 	eated (ac): 0.39 graphs 304 Description 303 Description 297 Description Description Description	rovided): unknown Re _v (provided):





304

303



New LID IMP SWM BMP Retrofit New	SWM BMP \Box	Type (Sheets 4 & 5):	40
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398747</u>	Y:	482490
Sketch Location of Footprint (with Approximate Dimer	isions) and Drainage	Boundary on Site Ma	p
Identify all Impairments Addressed by Recommendati	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW Count	y Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties: VES N	C		
Area Accessible for Construction:			
Area Accessible for Maintenance:			
Limited Permitting Issues: yes NO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: Vone Natural Gas Electric Tel	ephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Utilities Impacted: Vone Natural Gas Electric Tel	ephone 🗌 Cable 🗌 Wa	ter Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: YES VINO			
Mature / Specimen Trees Impacted:YESNO			
Existing Landscaping Impacted:			
Underdrain Needed: YES VO Under	rdrains Can Dischar	ge: 🗌 yes 🗌 no	
Soils are Suitable: VES NO Grou	nd Water Table Leve	el Suitable: 🖂 YES	NO
Estimate IMP / BMP drainage area included on site:	<u>0.35</u> a	с	95%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: YES NO	Add Aquatic Bench	I: YES NO	
Grade Bottom of Facility:YESNO	Plant Native Veget	ation: YES NO	
Provide Additional Storage Volume: YES NO			
Excavation / Raise the Embankment:	10		

IMP / BMP SUMN	IARY	
WQ _v (provided):	0.015	Re _v (provided): 0.0
Area Treated (ac):	0.28	Impervious Area Treated (ac): 0.
Photographs		
No. <u>298</u>	Description:	looking north
No. <u>302</u>	Description:	looking south
No.	Description:	
Comments Bioretention provide IMP size = 1,306 se	Bioretention will have a width of 6 es 79% treatment of drainage area q ft	





298

New LID IMP ☑ SWM BMP Retrofit □ Ne	w SWM BMP 🗌	Type (Sheets 4 & 5	5): <u>41</u>
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398892</u>	<u> </u>	Y: 482373
Sketch Location of Footprint (with Approximate Dim	nensions) and Draina	ge Boundary on Site M	Лар
Identify all Impairments Addressed by Recommend	lation (Sheet 1):		
Treatment Area Ownership: Transportation ROW	Utility ROW Cou	Inty Other Governmer	nt 🗹 Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties:	NO		
Area Accessible for Construction:	١O		
Area Accessible for Maintenance:	١O		
Limited Permitting Issues: yes NO			
Jurisdictional Wetlands Impacted:	١O		
Forest Retention Area Impacted:	١O		
Conservation Easement Impacted:	١O		
Utilities Present: 🖸 None 🗌 Natural Gas 🗌 Electric 🗌	Telephone Cable V	Water Sewer Othe	er
Utilities Impacted: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌	Telephone Cable V	Nater Sewer Othe	er
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: YES NO			
Mature / Specimen Trees Impacted:	0		
Existing Landscaping Impacted:	0		
Underdrain Needed: VES NO Un	derdrains Can Discha	arge: 🗹 YES 🗌 NO	
Soils are Suitable: YES NO Gr	ound Water Table Le	vel Suitable: 🗌 YES	NO
Estimate IMP / BMP drainage area included on site	<u>0.67</u>	ac	95%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: VES NO	Add Aquatic Ben	ch: YES NO	
Grade Bottom of Facility:YESNO	Plant Native Veg	etation: YES NC)
Provide Additional Storage Volume:YESNO			
Excavation / Raise the Embankment:	NO		

WQ _v (provided): Area Treated (ac): Photographs No. <u>305</u>	0.053 0.67	Re _v (provided): 0. Impervious Area Treated (ac): (
Photographs	0.67	Impervious Area Treated (ac):
No. 305		
	Description:	looking south
No. <u>306</u>	Description:	looking west
No. <u>307</u>	Description:	looking north
No. <u>308</u>	Description:	looking east
No.	Description:	
No	Description: Description:	0% treatment of drainage area using Filterra (to be





305

306





307

New LID IMP ☑ SWM BMP Retrofit □ New	SWM BMP 🗌	Type (Sheets 4 & 5)	38
State Plane Coordinates of IMP / BMP Centroid:	X: <u>1398762</u>	Y	482374
Sketch Location of Footprint (with Approximate Dimer	nsions) and Drainag	e Boundary on Site Ma	ар
Identify all Impairments Addressed by Recommendati	on (Sheet 1):		
Treatment Area Ownership:	Utility ROW Coun	ty Other Government	✓ Private
Infrastructure / Structures / Buildings Impacted:	YES 🗹 NO		
Limited Impact to Adjacent Properties:	0		
Area Accessible for Construction:			
Area Accessible for Maintenance:			
Limited Permitting Issues: yes NO			
Jurisdictional Wetlands Impacted:			
Forest Retention Area Impacted:			
Conservation Easement Impacted:			
Utilities Present: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tele	ephone 🗌 Cable 🗌 Wa	ater Sewer Other	
Utilities Impacted: 🗹 None 🗌 Natural Gas 🗌 Electric 🗌 Tele	ephone 🗌 Cable 🗌 Wa	ater Sewer Other	
Impacted Utilities: Above Gound Underground			
Critical Area Impacted: VES VNO			
Mature / Specimen Trees Impacted:YESNO			
Existing Landscaping Impacted:			
Underdrain Needed: YES VO Under	rdrains Can Discha	rge: 🗌 yes 🗌 no	
Soils are Suitable: 🖓 YES 🗌 NO Grou	nd Water Table Lev	el Suitable: 🖂 YES	NO
Estimate IMP / BMP drainage area included on site:	0.35	ac	95%
Retrofit of Existing SWM BMP			
SDI ID:	Add Forebay:	YES NO	
Modify Outlet Stucture: VES NO	Add Aquatic Benc	h: 🗌 yes 🗌 NO	
Grade Bottom of Facility:	Plant Native Vege	tation: YES NO	
Provide Additional Storage Volume: YES NO			
Excavation / Raise the Embankment:	NO		

IMP /	BMP SUMMA	RY		
WQ _v (provided): 0.007 Area Treated (ac): 0.13		0.007	Re _v (provided):	
		0.13	Impervious Area Treated (ac):	0.09
Photo	graphs			
No.	299	Description:	looking north	
No.	300	Description:	looking east	
No.	301	Description:	looking south	
No.		Description:		
Comm		IP will take up 3 parking spots.		
	ze = 605 sq ft	37% treatment of drainage area		
1111 312	<u>-0 – 000 34 ft</u>			





299

300

