

Catchment ID: UP02

### UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information

| Subwatershed:                                | <b>Upper Patuxent</b> |                         |                                |                |                      |        |              |     |
|--|-----------------------|-------------------------|--------------------------------|----------------|----------------------|--------|--------------|-----|
| Location of Catchment Centroid on ADC Map:   |                       | Year:                   | 2001                           | Page: <u>4</u> |                      | Grid:  | J4           |     |
| State Plane Coordinates of Outfall Location: |                       | X: <u> </u>             | 1357218                        |                | Y:                   | 519332 |              |     |
| Closest Road Inte                            | ersection to Outfall  | : Laurel Bowie          | Road and                       | Morris Driv    | ve                   |        |              |     |
| Outfall SDI ID or                            | Outfall Description   | SDI 55261               |                                |                |                      |        |              |     |
| Objective: Demo                              | nstration / Impairm   | nent(s) (Sheet 1        | ) _                            |                |                      |        |              |     |
| Drainage Area (ad                            | c): <u>25.7</u>       |                         | Imperv                         | ious Area      | a (ac): <u>1</u>     | 4.0    |              |     |
| Percent Impervious: 55%                      |                       |                         | Soil Recharge Factor (S): 0.08 |                |                      |        |              |     |
| WQ <sub>v</sub> (required):                  | 1.17                  |                         | Re <sub>v</sub> (re            | quired): (     | 0.10                 |        |              |     |
| Predominant Land                             | d Use: parking lot (  | commercial)             | Mean I                         | Depth to (     | Ground Wate          | r:     | 0-1 ft       |     |
| Sanitary System:                             | ☐ Septic ✓ Mur        | nicipal Sewer           | Water                          | Supply:        | On Site Well         | ✓      | Public Water |     |
| Storm Drainage                               | System Within         | Catchment               |                                |                |                      |        |              |     |
| Piped: 100%                                  | <u>6</u> Open         | Channels:               | 0%                             |                |                      |        |              |     |
| Area Drained by S                            | System:               | 100%                    |                                |                |                      |        |              |     |
| Location in Catch                            | ment: Headwate        | rs Middle               | Lower                          | ✓ AII          |                      |        |              |     |
| Open Channel Lir                             | ning- Vegetation:     | 0%                      | Riprap:                        | 0%             | Concrete:            | 0%     | Other:       | 0%  |
| Existing IMP(s)                              | /BMP(s)               |                         |                                |                |                      |        |              |     |
| SDI ID: <u>55241</u>                         | Type (numb            | er from Sheet           | s 4 & 5): <u> </u>             | oond           | Age: _               |        | _            |     |
| Closest Road Inte                            | ersection to IMP / E  | BMP: <u>Laur</u>        | el Bowie I                     | Road and       | Morris Drive         |        |              |     |
| Catchment Area                               | Treated (ac): 14      | .8                      | Per                            | centage C      | Catchment Tr         | eated: |              | 57% |
| WQ <sub>v</sub> Provided:                    | ☐YES ☑NO              | Re <sub>v</sub> Provide | d: YES                         | ✓NO            | C <sub>p</sub> Provi | ded:   | YES          | ✓NO |
| SDI ID:                                      | Type (numb            | er from Sheet           | s 4 & 5): _                    |                | Age:                 |        | _            |     |
| Closest Road Inte                            | ersection to IMP / E  | BMP:                    |                                |                |                      |        |              |     |
| Catchment Area                               | Treated (ac):         |                         | Per                            | centage C      | Catchment Tr         | eated: |              |     |
| WQ <sub>v</sub> Provided:                    | YES NO                | Re <sub>v</sub> Provide | d: YES                         | □no            | C <sub>p</sub> Provi | ded:   | YES          | □NO |
| SDI ID:                                      | _ Type (numb          | er from Sheet           | s 4 & 5): _                    |                | Age:                 |        | _            |     |
| Closest Road Inte                            | ersection to IMP / E  | BMP:                    |                                |                |                      |        |              |     |
| Catchment Area                               | Treated (ac):         |                         | Per                            | centage C      | Catchment Tr         | eated: |              |     |
| WQ <sub>v</sub> Provided:                    | YES NO                | Re <sub>v</sub> Provide | d: YES                         | □NO            | C <sub>p</sub> Provi | ded:   | YES          | □NO |

Catchment ID: UP02

# UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information (concluded)

| CATCHMENT SUMMARY           |                               |  |  |  |  |  |
|-----------------------------|-------------------------------|--|--|--|--|--|
| WQ <sub>v</sub> (provided): | Re <sub>v</sub> (provided) :  |  |  |  |  |  |
| Area Treated (ac):          | Impervious Area Treated (ac): |  |  |  |  |  |
| Area Treated (%):           | Impervious Area Treated (%):  |  |  |  |  |  |
| Comments                    |                               |  |  |  |  |  |
|                             |                               |  |  |  |  |  |
|                             |                               |  |  |  |  |  |
|                             |                               |  |  |  |  |  |
|                             |                               |  |  |  |  |  |

Site ID: HDL Catchment ID: UP02

### UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information

| Site Name: Home Depot, Laurel                    | Address: 208 Fort Meade Road, Laurel MD, 20708          |
|--|---|
| Site Owner: Home Depot U.S.A. Inc.               |   |
| State Plane Coordinates of Site Centroid:        | X: <u>1357724</u> Y: <u>519710</u> Date: <u>3/25/03</u> |
| Personnel: PM                                    | Weather: sunny, 75F deg                                 |
| Area (ac): <u>12.1</u>                           | Impervious Area (ac): 7.8                               |
| Percent Impervious: 64%                          | Soil Recharge Factor (S): 0.07                          |
| WQ <sub>v</sub> (required): 0.63                 | Re <sub>v</sub> (required): 0.05                        |
| Property Area (ac): 16.2                         | Property Area Included in Site: 75 %                    |
| Amount of Catchment Occupied by Site:            | <u>47</u> %   |
|  |   |
| Storm Drainage System Within Site                |   |
|  | 0% Area Drained by System: 100%                         |
| Open Channel Lining - Vegetation:0% Ri           | prap: 0% Concrete: 0% Other: 0%                         |
| Existing IMP(s) / BMP(s) (Indentified on Pa      | age 1. FORM 1. Catchment Information)                   |
|  | dition: ☐ Excellent ☑ Good ☐ Average ☐ Fair ☐ Poor      |
|  | dition: ☐ Excellent ☐ Good ☐ Average ☐ Fair ☐ Poor      |
|  | dition: ☐ Excellent ☐ Good ☐ Average ☐ Fair ☐ Poor      |
|  |   |
| Site Information                                 |   |
| Type of Pavement:                                | Gravel Grid Pavers Other                                |
| Pavement Condition:                              | ood 🗹 Average 🔲 Fair 🔲 Poor                             |
| Underdrains can be easily directed to existing s | torm drains or daylighted: ☑ YES ☐ NO                   |
| Gutter/Exterior Downspouts Present:              | S NO  |
| Roof Connected Directly to Storm Drain: 💟 YES    | S NO  |
| Roof Drains onto Impervious Surface:             | S NO  |
| Obvious Existing Drainage Problems:              | Extensive  Moderate  Average  Limited  Mone             |
| Steep Slopes Present:   Extensive   M            | oderate Average Limited ✓ None                          |
| Existing Landscaping:                            | oderate 🗹 Average 🔲 Limited 🔲 None                      |
| Mature / Specimen Trees:                         | oderate Average Limited 🗸 None                          |
| Area Available for Aboveground BMPs:             | Extensive  Moderate  Average  Limited  None             |
| Existing Cover of Potential Aboveground BMP I    |   |
|  | ✓ Pavement ☐ Other Impervious                           |

Site ID: HDL Catchment ID: UP02

# UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)

| Com      | mercial / Inst    | tutional   |                               |  |  |  |  |  |
|----------|-------------------|--|-------------------------------|--|--|--|--|--|
| Island   | ds Present: 🗹     | Curb Present Around Island: YES NO   |                               |  |  |  |  |  |
| Grou     | nd Level of Islar | d Relative to Pavement: ☑ Above ☐ Equal ☐ Below  |                               |  |  |  |  |  |
| Island   | d Landscaping:    | ☐ Impervious ☐ Bare Earth ☐ Gravel ☑ Grass ☐ Mulch ☑ Herbaceous Plants ☑ Shrubs ☐ Trees (<2 in. DBH) ☐ Trees (>6 in. DBH) ☐ Trees (>6 in. DBH)                     | S                             |  |  |  |  |  |
| Trees    | have sufficient   | spacing to allow IMPs  |                               |  |  |  |  |  |
| Parki    | ng area that car  | be directed to potential treatment area with little grading: 95%   |                               |  |  |  |  |  |
| SITE     | SUMMARY           |  | _                             |  |  |  |  |  |
| $WQ_v$   | (provided):       | Re <sub>v</sub> (provided):  |                               |  |  |  |  |  |
| Area     | Treated (ac) :    | Impervious Area Treated (ac):  | Impervious Area Treated (ac): |  |  |  |  |  |
| Area     | Treated (%):      | Impervious Area Treated (%):   |                               |  |  |  |  |  |
| Phot     | ographs           |  |                               |  |  |  |  |  |
| No.      | 441               | Description: looking northeast across stormwater pond  |                               |  |  |  |  |  |
| No.      | 442               | Description: looking southeast to front (north) side of building   |                               |  |  |  |  |  |
| No.      | 443               | Description: looking southwest to front (north) side of building   |                               |  |  |  |  |  |
| No.      | 444               | Description: looking northeast to back (south) side of building  |                               |  |  |  |  |  |
| No.      | 445               | Description: looking northeast at south outfall vicinity   |                               |  |  |  |  |  |
| No.      | 446               | Description: looking northeast at west side of building  |                               |  |  |  |  |  |
| No.      | 447               | Description: looking west at stormwater pond   |                               |  |  |  |  |  |
| No.      | 448               | Description: looking east across stormwater pond   |                               |  |  |  |  |  |
| No.      | 449               | Description: looking northeast across parking lot  |                               |  |  |  |  |  |
| No.      |                   | Description:   |                               |  |  |  |  |  |
| Comments |                   | Recently remodeled from a Hechengers to a Home Depot. Roof drains to back (south) side of building. A large amount of dumping (car batteries included) is present. |                               |  |  |  |  |  |
|          |                   |  |                               |  |  |  |  |  |
|          |                   |  |                               |  |  |  |  |  |
|          |                   |  | _                             |  |  |  |  |  |
|          |                   |  |                               |  |  |  |  |  |
|          |                   |  |                               |  |  |  |  |  |

#### UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information





441 442





443 444





445 446

Site ID: <u>HDL</u> Catchment ID: <u>UP02</u>

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)





447 448



449