

### UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information

Subwatershed: Tributary 1				
Location of Catchment Centroid on ADC Map:	Year: 2001 Page: 10 Grid: B10			
State Plane Coordinates of Outfall Location:	X: <u>1383461</u> Y: <u>482410</u>			
Closest Road Intersection to Outfall: Whitehall Drive	and Westmore Court			
Outfall SDI ID or Outfall Description: headwaters of	Tributary 1			
Objective: Demonstration / Impairment(s) (Sheet 1)				
Drainage Area (ac): 11.3	Impervious Area (ac): <u>3.1</u>			
Percent Impervious: 28%	Soil Recharge Factor (S): 0.29			
WQ <sub>v</sub> (required): 0.28	Re <sub>v</sub> (required): 0.08			
Predominant Land Use: <u>school</u>	Mean Depth to Ground Water: >=5ft			
Sanitary System: Septic Municipal Sewer	Water Supply: On Site Well Vublic Water			
Storm Drainage System Within Catchment				
Piped: 20% Open Channels:	80%_			
Area Drained by System: 100%				
Location in Catchment: Headwaters Middle	Lower I All			
Open Channel Lining- Vegetation: 100%	Riprap:   0%   Concrete:   0%   Other:   0%			
Existing IMP(s) / BMP(s)				
SDI ID: Type (number from Sheets	4 & 5): Age:			
Closest Road Intersection to IMP / BMP:				
Catchment Area Treated (ac) :	Percentage Catchment Treated:			
WQ <sub>v</sub> Provided: $\square$ YES $\square$ NO Re <sub>v</sub> Provided:				
SDI ID: Type (number from Sheets	4 & 5): Age:			
Closest Road Intersection to IMP / BMP:				
Catchment Area Treated (ac) :				
WQ <sub>v</sub> Provided: $\Box$ YES $\Box$ NO Re <sub>v</sub> Provided:				
SDI ID: Type (number from Sheets	4 & 5): Age:			
Closest Road Intersection to IMP / BMP:				
Catchment Area Treated (ac) :	Percentage Catchment Treated:			
$WQ_v$ Provided: $\Box_{YES}$ $\Box_{NO}$ Re <sub>v</sub> Provided:	YES NO C <sub>p</sub> Provided: YES NO			

# UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 1 -- Catchment Information (concluded)

CATCHMENT SUMMARY		
WQ <sub>v</sub> (provided):	Re <sub>v</sub> (provided) :	
Area Treated (ac):	Impervious Area Treated (ac):	
Area Treated (%):	Impervious Area Treated (%):	
Comments		

### UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information

Site Name: William Irwin Buck Center	Address: Old Chapel Road, Lanham MD			
Site Owner: United Cerebral Palsy Association of	of Prince Georges County Inc.			
State Plane Coordinates of Site Centroid:	X: <u>1383045</u> Y: <u>481884</u> Date: <u>4/2/03</u>			
Personnel: <u>PM</u>	Weather: <u>sunny, 80F deg</u>			
Area (ac): 9.3	Impervious Area (ac): 2.8			
Percent Impervious:30%WQv (required):0.25	Soil Recharge Factor (S): $0.3$ $Re_v$ (required): $0.07$			
Property Area (ac): 9.8	Property Area Included in Site: <u>95</u> %			
Amount of Catchment Occupied by Site:	82 %			
	80% Area Drained by System: 100%			
Open Channel Lining - Vegetation: 100%	Riprap:   0%   Concrete:   20%   Other:   0%			
Existing IMP(s) / BMP(s) (Indentified on	Page 1, FORM 1, Catchment Information)			
SDI ID: Co	Dindition: Excellent Good Average Fair Poor			
	Dindition: Excellent Good Average Fair Poor			
SDI ID: Co	Dindition: Excellent Good Average Fair Poor			
Site Information				
Type of Pavement:   Bituminous  Concret	e 🔲 Gravel 🔲 Grid Pavers 🔲 Other			
	Good ☐ Average ☑ Fair ☐ Poor			
Underdrains can be easily directed to existing	•			
	YES VNO			
Roof Connected Directly to Storm Drain: VIS INO				
Roof Drains onto Impervious Surface:	YES NO			
Obvious Existing Drainage Problems:	Extensive Moderate Average Limited None			
Steep Slopes Present:	Moderate Average Limited 🗹 None			
Existing Landscaping:	Moderate Average 🗹 Limited 🗌 None			
Mature / Specimen Trees:	Moderate 🗹 Average 🔲 Limited 🗹 None			
Area Available for Aboveground BMPs:	Extensive Moderate Average Limited None			
Existing Cover of Potential Aboveground BM	P Locations:			

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)

Commercial / Institutional					
Islands Present: VES NO	Curb Present Around Island: VES NO				
Ground Level of Island Relative to Pavement: Above					
Island Landscaping: Impervious Trees (<2 in. DBH	Bare Earth       Gravel       Grass       Mulch       Herbaceous Plants       Shrubs         H)       Trees (2 - 6 in. DBH)       Trees (>6 in. DBH)				
Trees have sufficient spacing to allow I	Trees have sufficient spacing to allow IMPs VES NO				
Parking area that can be directed to potential treatment area with little grading: 100%					
SITE SUMMARY					
WQ <sub>v</sub> (provided) :	Re <sub>v</sub> (provided):				
Area Treated (ac) :	Impervious Area Treated (ac):				
Area Treated (%) :	Impervious Area Treated (%):				

\_

### **Photographs**

No.	500	Description: looking southwest at southeast side of building
No.	501	Description: looking southeast at north end of building
No.	502	Description: looking southwest at west end of building
No.	503	Description: looking northeast at west end of building
No.	504	Description: looking east at south end of building
No.	505	Description: looking northeast at southwest (front) side of building
No.	506	Description: looking northeast at southeast side of building
No.	507	Description: looking northwest at southwest (front) side of building
No.		Description:
No.		Description:

#### Comments

### UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information







501



502



503



504

505

### UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information (concluded)





506

507